
## **VENTILATION AUDIT REPORT Version 2**



SCHOOL:	Riverina Environmental Education Centre (5734)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Wagga Wagga
LOCAL GOVERNMENT AREA:	Wagga Wagga



Site plan is indicative only and is included to show building numbers used by the Department.

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
•	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Laboratory L.S (45.24 SQM) - Teaching Space: 1	Student Space (24)	
B00A - R0007 - Materials Technology L.S (26.74 SQM) - Teaching Space: 1	Student Space (14)	
B00B - R0001 - Staff Room - (23.52 SQM)	Office (5)	
B00E - R0001 - Practical Activities - (54.11 SQM)	Student Space (25)	
OS 601 10790 - OS 601 10790 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	
OS 750 12466 - OS 750 12466 - Learning Unit - ESL - (38 SQM)	Student Space (17)	