
VENTILATION AUDIT REPORT Version 2



SCHOOL:	Spring Terrace Public School (3093)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Orange
LOCAL GOVERNMENT AREA:	Cabonne

3093 - Spring Terrace Public School Site Plan (13458)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (57.62 SQM) - Teaching Space: 1	Student Space (52)	
B00A - R0003 - Clerical Office - (15.52 SQM)	Office (3)	
B00A - R0004 - Reading Area - (12.93 SQM)	Student Space (5)	
B00F - R0001 - Communal Space - (59.74 SQM)	Student Space (27)	
OS 500 18119 - OS 500 18119 - Admin - Library - (133 SQM)	Office (33)	
OS 601 13781 - OS 601 13781 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	