
VENTILATION AUDIT REPORT Version 2



SCHOOL:	Wilsons Creek Public School (3454)
AMU REGION:	North Coast
STATE ELECTORATE:	Ballina
LOCAL GOVERNMENT AREA:	Byron

3454 - Wilsons Creek Public School Site Plan (13525)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (11.12 SQM)	Office (2)	
B00A - R0002 - Principal - (11.35 SQM)	Office (2)	
B00A - R0004 - Entry Vestibule - (13.32 SQM)	Not Applicable	Circulation or storage space.
B00A - R0006 - Home Base - (63.66 SQM) - Teaching Space: 1	Student Space (49)	
B00A - R0010 - Principal - (16.53 SQM)	Office (4)	
B00A - R0011 - Withdrawal Space - 1hb - (14.28 SQM)	Student Space (6)	
B00A - R0012 - Canteen - (21.4 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Canteen - (12.66 SQM)	Not Applicable	Circulation or storage space.
B00B - R0003 - Staff Room - (41.49 SQM)	Office (10)	
B00E - R0002 - Special Programs Room - (51.44 SQM)	Student Space (23)	
B00F - R0002 - Reading Area - (93.06 SQM)	Student Space (43)	
OS 601 10251 - OS 601 10251 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	
OS 601 10385 - OS 601 10385 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	