


VENTILATION AUDIT REPORT Version 2

SCHOOL:	Wyaliba Public School (4556)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Northern Tablelands
LOCAL GOVERNMENT AREA:	Glen Innes Severn







4556 - Wyaliba Public School
Site Plan (10586)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00E - R0001 - Reading Area - (60 SQM)	 Student Space (27)	
B00G - R0001 - Home Base - (61.53 SQM) - Teaching Space: 1	 Student Space (65)	
OS 522 17399 - OS 522 17399 - Staff Study - (38 SQM)	 Office (9)	
OS 523 70003 - OS 523 70003 - Staff Study With Toilets - (76 SQM)	 Office (19)	
OS 606 19735 - OS 606 19735 - Learning Unit - Standard With P.A.A A/C - (76 SQM)	 Student Space (35)	
OS 750 11573 - OS 750 11573 - Learning Unit - ESL - (38 SQM)	 Student Space (17)	