VENTILATION AUDIT REPORT Version 2



SCHOOL:	Yarrowitch Public School (3547)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Walcha

3547 - Yarrowitch Public School Site Plan (11476)



Site plan is indicative only and is included to show building numbers used by the Department.

Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Reading Area - (46.24 SQM)	Student Space (21)	
B00A - R0003 - Home Base - (54.33 SQM) - Teaching Space: 1	Student Space (42)	
B00A - R0005 - Principal - (13.48 SQM)	Office (3)	
B00A - R0006 - Movement - (12.8 SQM)	Not Applicable	Circulation or storage space.
B00A - R0009 - Principal - (17.7 SQM)	Office (4)	
B00C - R0001 - Movement - (26.58 SQM)	Not Applicable	Circulation or storage space.
B00E - R0002 - Reading Area - (61.39 SQM)	Student Space (28)	