
VENTILATION AUDIT REPORT



SCHOOL:	Adaminaby Public School (1007)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Monaro
LOCAL GOVERNMENT AREA:	Snowy Monaro



1007 - Adaminaby Public School Site Plan (11722)

1:819

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
\bigcirc	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00B - R0002 - Movement - (9.75 SQM)	Not Applicable	Circulation or storage space.
B00B - R0003 - Reading Area - (41.47 SQM)	Student Space (19)	
B00C - R0001 - Movement - (21.63 SQM)	Not Applicable	Circulation or storage space.
B00C - R0010 - Home Base - (52.71 SQM) - Teaching Space: 1	Student Space (24)	
B00C - R0011 - Home Base - (66.8 SQM) - Teaching Space: 1	Student Space (30)	
B00C - R0012 - Withdrawal Space - 1hb - (7.2 SQM)	Student Space (3)	
B00C - R0014 - Sick Bay - (7.26 SQM)	Student Space (3)	
B00C - R0015 - Movement - (8.94 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Reading Area - (140.3 SQM)	Student Space (65)	
OS 505 13454 - OS 505 13454 - Admin Staff/Principal/Secure Store - (76 SQM)	Office (19)	