


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Albury Tutorial Centre (889)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	
<b>LOCAL GOVERNMENT AREA:</b>	

Siteplan

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Seminar Space - (13.78 SQM)	 Office (3)	
B00A - R0003 - Independent Learning Space - (37.99 SQM)	 Student Space (17)	
B00B - R0001 - Independent Learning Space - (38.04 SQM)	 Student Space (17)	
B00B - R0002 - Seminar Space - (13.73 SQM)	 Office (3)	