

VENTILATION AUDIT REPORT



SCHOOL:	Avoca Public School (1081)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Goulburn
LOCAL GOVERNMENT AREA:	Wingecarribee





Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (11.99 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Clerical Office/Workroom - (17.29 SQM)	Office (4)	
B00A - R0003 - Reading Area - (46.12 SQM)	Student Space (21)	
B00D - R0001 - Staff Room - (20.38 SQM)	Office (5)	
B00E - R0001 - Movement - (42.67 SQM)	Not Applicable	Circulation or storage space.
B00F - R0001 - Entry Vestibule - (14.48 SQM)	Not Applicable	Circulation or storage space.
B00F - R0002 - Principal - (13.47 SQM)	Office (3)	
B00F - R0003 - Clerical Office/Workroom - (13.4 SQM)	Office (3)	
B00F - R0005 - Staff Room - (13.29 SQM)	Office (3)	
B00F - R0006 - Movement - (9.96 SQM)	Not Applicable	Circulation or storage space.
B00F - R0007 - Movement - (7.65 SQM)	Not Applicable	Circulation or storage space.
B00F - R0008 - Staff Kitchen - (12.4 SQM)	Office (3)	
B00F - R0013 - Clerical Office - (15.32 SQM)	Office (3)	
B00F - R0014 - Sick Bay - (11.26 SQM)	Student Space (5)	
B00H - R0004 - Home Base - (60.93 SQM) - Teaching Space: 1	Student Space (28)	
OS 601 10864 - OS 601 10864 - Learning Unit - Standard/Withdrawal - (76 SQM)	Student Space (35)	