

VENTILATION AUDIT REPORT



SCHOOL:	Awaba Public School (1084)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Lake Macquarie
LOCAL GOVERNMENT AREA:	Lake Macquarie





Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
•	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (49.72 SQM) - Teaching Space: 1	Student Space (23)	
B00A - R0002 - Principal - (13.28 SQM)	Office (3)	
B00A - R0003 - Clerical Office - (13.28 SQM)	Office (3)	
B00A - R0004 - Movement - (24.86 SQM)	Not Applicable	Circulation or storage space.
B00A - R0005 - Staff Room - (18.18 SQM)	Office (4)	
B00B - R0002 - Home Base - (46.79 SQM) - Teaching Space: 1	Student Space (21)	
B00B - R0003 - Movement - (7.03 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Staff Room Annexe - (10.24 SQM)	Office (2)	
B00C - R0003 - Home Base - (43.7 SQM) - Teaching Space: 1	Student Space (20)	
B00C - R0005 - Canteen - (10.21 SQM)	Not Applicable	Circulation or storage space.
B00C - R0006 - Movement - (6.7 SQM)	Not Applicable	Circulation or storage space.
B00C - R0008 - Withdrawal Space - 1hb - (5.29 SQM)	Student Space (2)	
B00D - R0001 - Movement - (9.63 SQM)	Not Applicable	Circulation or storage space.
OS 500 18115 - OS 500 18115 - Admin - Library - (133 SQM)	Office (33)	