

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Bardwell Park Infants School (5148)</b>
<b>AMU REGION:</b>	<b>Sydney</b>
<b>STATE ELECTORATE:</b>	<b>Rockdale</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Bayside</b>

5148 - Bardwell Park Infants School  
Site Plan (12310)













1:411

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Principal - (18.13 SQM)	 Office (4)	
B00A - R0006 - Home Base - (56.81 SQM) - Teaching Space: 1	 Student Space (26)	
B00A - R0007 - Home Base - (84.3 SQM) - Teaching Space: 1	 Student Space (39)	
B00A - R0012 - Staff Room - (20.35 SQM)	 Office (5)	
B00A - R0016 - Clerical Office/Workroom - (27.35 SQM)	 Office (6)	
B00B - R0001 - Movement - (38.48 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Practical Activities - 1hb - (19.36 SQM)	 Student Space (8)	
B00B - R0004 - Home Base - (58.76 SQM) - Teaching Space: 1	 Student Space (27)	
B00B - R0005 - Withdrawal Space - 2hb - (10.67 SQM)	 Student Space (4)	
B00B - R0006 - Home Base - (58.67 SQM) - Teaching Space: 1	 Student Space (27)	
B00B - R0008 - Practical Activities - 1hb - (19.36 SQM)	 Student Space (8)	