

VENTILATION AUDIT REPORT

SCHOOL:	Barrington Public School (1143)
AMU REGION:	North Coast
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Mid-Coast

1143 - Barrington Public School
Site Plan (10173)











1:551

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Home Base - (60.19 SQM) - Teaching Space: 1	 Student Space (27)	
B00F - R0002 - Practical Activities - 1hb - (19.36 SQM)	 Student Space (8)	
B00F - R0004 - Home Base - (58.76 SQM) - Teaching Space: 1	 Student Space (27)	
B00F - R0005 - Withdrawal Space - 2hb - (10.67 SQM)	 Student Space (4)	
B00F - R0006 - Home Base - (58.67 SQM) - Teaching Space: 1	 Student Space (27)	
B00F - R0008 - Practical Activities - 1hb - (19.36 SQM)	 Student Space (8)	
OS 503 15543 - OS 503 15543 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	 Office (38)	
OS 531 15881 - OS 531 15881 - Library - (76 SQM)	 Student Space (35)	