


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Beckom Public School (1160)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Cootamundra</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Coolamon</b>

1160 - Beckom Public School  
Site Plan (10602)








1:1,012

Printed: 15-Aug-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (41.11 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Principal - (14.02 SQM)	 Office (3)	
B00A - R0007 - Home Base - (57.05 SQM) - Teaching Space: 1	 Student Space (26)	
B00A - R0008 - Home Base - (57.68 SQM) - Teaching Space: 1	 Student Space (26)	
B00A - R0012 - Clerical Office - (21.19 SQM)	 Office (5)	
B00F - R0001 - Reading Area - (59.87 SQM)	 Student Space (27)	