


VENTILATION AUDIT REPORT

SCHOOL:	Bellata Public School (1175)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Narrabri

1175 - Bellata Public School
Site Plan (13519)














1:205

Printed: 17-Apr-2021

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Canteen - (23.18 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Clerical Office - (23.3 SQM)	 Office (5)	
B00A - R0009 - Principal - (10.93 SQM)	 Office (2)	
B00A - R0010 - Clerical Office/Workroom - (11.2 SQM)	 Office (2)	
B00A - R0013 - Reading Area - (64.78 SQM)	 Student Space (30)	
B00A - R1002 - Practical Activities - 1hb - (8.4 SQM)	 Student Space (3)	
B00A - R1003 - Staff Room Annexe - (7.79 SQM)	 Office (1)	
B00A - R1005 - Home Base - (46.83 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R1006 - Home Base - (46.83 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R1007 - Staff Room - (13.31 SQM)	 Office (3)	
B00B - R1001 - Home Base - (53.29 SQM) - Teaching Space: 1	 Student Space (24)	
B00B - R1002 - Practical Activities - 1hb - (16.06 SQM)	 Student Space (7)	