

VENTILATION AUDIT REPORT

SCHOOL:	Bellbrook Public School (1178)
AMU REGION:	North Coast
STATE ELECTORATE:	Oxley
LOCAL GOVERNMENT AREA:	Kempsey

1178 - Bellbrook Public School
Site Plan (10871)











1:535

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Practical Activities - 1hb - (19.35 SQM)	 Student Space (8)	
B00A - R0003 - Entry Vestibule - (9.79 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Practical Activities - 1hb - (23.53 SQM)	 Student Space (10)	
B00A - R0005 - Home Base - (53.73 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0006 - Duplicating Workroom - (10.86 SQM)	 Office (2)	
B00A - R0007 - Clerical Office - (11.1 SQM)	 Office (2)	
B00A - R0009 - Reading Area - (23.76 SQM)	 Student Space (11)	
B00A - R0010 - Canteen - (15.09 SQM)	Not Applicable	Circulation or storage space.
B00A - R0011 - Home Base - (47.6 SQM) - Teaching Space: 1	 Student Space (22)	
OS 500 18108 - OS 500 18108 - Admin - Library - (133 SQM)	 Office (33)	