


VENTILATION AUDIT REPORT









SCHOOL:	Belltrees Public School (1182)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Upper Hunter

1182 - Belltrees Public School
Site Plan (12324)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - M0001 - Withdrawal Space - 1hb - (5.72 SQM)	 Student Space (2)	
B00A - R0001 - Practical Activities - 1hb - (16.35 SQM)	 Student Space (7)	
B00A - R0002 - Reading Area - (16.91 SQM)	 Student Space (7)	
B00A - R0004 - Home Base - (47.6 SQM) - Teaching Space: 1	 Student Space (22)	
B00A - R0005 - Principal - (12.96 SQM)	 Office (3)	
B00A - R0007 - Movement - (51.9 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Home Base - (59.2 SQM) - Teaching Space: 1	 Student Space (27)	
B00D - R0002 - Reading Area - (53.94 SQM)	 Student Space (25)	
B00D - R0003 - Principal - (10.36 SQM)	 Office (2)	