


VENTILATION AUDIT REPORT

SCHOOL:	Ben Lomond Public School (1196)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Northern Tablelands
LOCAL GOVERNMENT AREA:	Armidale

1196 - Ben Lomond Public School
Site Plan (12328)













1:551

Printed: 03-Aug-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Home Base - (53.44 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0003 - Home Base - (53.44 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0005 - Withdrawal Space - 1hb - (8.76 SQM)	 Student Space (4)	
B00A - R0007 - Sick Bay - (6.24 SQM)	 Student Space (2)	
B00A - R0008 - Practical Activities - 1hb - (33.37 SQM)	 Student Space (15)	
B00A - R0009 - Movement - (5.7 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Movement - (18.48 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Reading Area - (28.69 SQM)	 Student Space (13)	
B00C - R0003 - Entry Vestibule - (12 SQM)	Not Applicable	Circulation or storage space.
B00C - R0004 - Principal - (12.76 SQM)	 Office (3)	
B00C - R0006 - Staff Room - (25.56 SQM)	 Office (6)	
B00C - R0007 - Clerical Office/Workroom - (22.71 SQM)	 Office (5)	
B00C - R0008 - Movement - (8.07 SQM)	Not Applicable	Circulation or storage space.
B00F - R0001 - Communal Space - (146.3 SQM)	 Student Space (67)	