


VENTILATION AUDIT REPORT

SCHOOL:	Bendemeer Public School (1191)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Tamworth

1191 - Bendemeer Public School
Site Plan (10774)







1:868

Printed: 07-Nov-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Reading Area - (46.83 SQM)	 Student Space (21)	
B00A - R0005 - Home Base - (47.01 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0008 - Home Base - (67.07 SQM) - Teaching Space: 1	 Student Space (31)	
B00A - R0013 - Movement - (14.51 SQM)	Not Applicable	Circulation or storage space.
B00A - R0014 - Movement - (55.86 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Movement - (35.2 SQM)	Not Applicable	Circulation or storage space.
B00F - R0005 - Reading Area - (72.12 SQM)	 Student Space (33)	