


VENTILATION AUDIT REPORT

SCHOOL:	Binda Public School (1231)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Goulburn
LOCAL GOVERNMENT AREA:	Upper Lachlan

1231 - Binda Public School
Site Plan (10882)









1:748

Printed: 17-Sep-2021

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Staff Kitchen - (8.7 SQM)	 Office (2)	
B00A - R0002 - Home Base - (46.72 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0004 - Home Base - (46.72 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0005 - Withdrawal Space - 1hb - (9.65 SQM)	 Student Space (4)	
B00A - R0007 - Entry Vestibule - (11.29 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Clerical Office/Workroom - (27.9 SQM)	 Office (6)	
B00C - R0001 - Movement - (112.62 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Communal Space - (58.25 SQM)	 Student Space (27)	