

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Binya Public School (1238)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Cootamundra</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Narrandera</b>

1238 - Binya Public School  
Site Plan (11951)









1:626

Printed: 17-Dec-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0008 - Principal - (11.49 SQM)	 Office (2)	
B00A - R0010 - Entry Vestibule - (7.08 SQM)	Not Applicable	Circulation or storage space.
B00A - R0012 - Clerical Office/Workroom - (25.07 SQM)	 Office (6)	
B00B - R0002 - Movement - (31.32 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Clerical Office - (16.8 SQM)	 Office (4)	
B00C - R0002 - Practical Activities - 1hb - (10.5 SQM)	 Student Space (4)	
B00C - R0003 - Home Base - (53.21 SQM) - Teaching Space: 1	 Student Space (24)	
B00C - R0005 - Reading Area - (52.41 SQM)	 Student Space (24)	