

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Black Springs Public School (4190)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Bathurst</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Oberon</b>

4190 - Black Springs Public School  
Site Plan (10886)



1:759

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (16.01 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Movement - (45.09 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Home Base - (56.28 SQM) - Teaching Space: 1	● Student Space (26)	
B00B - R0003 - Principal - (13.04 SQM)	● Office (3)	
B00B - R0005 - Home Base - (53.17 SQM) - Teaching Space: 1	● Student Space (24)	
B00B - R0009 - Movement - (8.26 SQM)	Not Applicable	Circulation or storage space.
B00B - R0011 - Staff Room - (17.42 SQM)	● Office (4)	
B00B - R0013 - Clerical Office - (6.41 SQM)	● Office (1)	
B00C - R0001 - Special Programs Room - (22.13 SQM)	● Student Space (10)	
B00C - R0002 - Special Programs Room - (11.89 SQM)	● Student Space (5)	
B00D - R0001 - Reading Area - (53.46 SQM)	● Student Space (24)	
B00D - R0003 - Movement - (20.73 SQM)	Not Applicable	Circulation or storage space.