






VENTILATION AUDIT REPORT

| | |
|-------------------------------|--|
| SCHOOL: | Blacktown Tutorial Centre (883) |
| AMU REGION: | Western Sydney |
| STATE ELECTORATE: | Blacktown |
| LOCAL GOVERNMENT AREA: | |

Siteplan

Ventilation Audit Key

| Category | Description |
|---|--|
|  | Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings. |
|  | Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces. |

| Entity Location | Audit Condition Classification (Capacity) | Comment |
|---|--|---------|
| B00A - R0008 - Independent Learning Space - (64.98 SQM) |  Student Space (30) | |
| B00A - R0015 - Independent Learning Space - (65.06 SQM) |  Student Space (30) | |
| B00A - R0016 - Independent Learning Space - (65.07 SQM) |  Student Space (30) | |
| B00A - R0023 - Clerical Office - (7.45 SQM) |  Office (1) | |
| B00A - R0026 - Kitchen - Type 1 - (21.36 SQM) |  Student Space (9) | |