


VENTILATION AUDIT REPORT

SCHOOL:	Blakebrook Public School (1254)
AMU REGION:	North Coast
STATE ELECTORATE:	Lismore
LOCAL GOVERNMENT AREA:	Lismore

1254 - Blakebrook Public School
Site Plan (11779)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Reading Area - (53.94 SQM)	● Student Space (25)	
B00C - R0001 - Canteen - (13.2 SQM)	Not Applicable	Circulation or storage space.
B00E - R0003 - Practical Activities - 1hb - (10.03 SQM)	● Student Space (4)	
B00E - R0004 - Home Base - (54.66 SQM) - Teaching Space: 1	● Student Space (25)	
B00F - R0005 - Home Base - (53.03 SQM) - Teaching Space: 1	● Student Space (24)	
B00I - R0002 - Practical Activities - 1hb - (19.41 SQM)	● Student Space (9)	
B00I - R0004 - Home Base - (58.92 SQM) - Teaching Space: 1	● Student Space (27)	
B00I - R0005 - Withdrawal Space - 2hb - (10.7 SQM)	● Student Space (4)	
B00I - R0006 - Home Base - (58.82 SQM) - Teaching Space: 1	● Student Space (27)	
B00I - R0008 - Practical Activities - 1hb - (19.41 SQM)	● Student Space (9)	
OS 500 18129 - OS 500 18129 - Admin - Library - (133 SQM)	● Office (33)	