

VENTILATION AUDIT REPORT

SCHOOL:	Blandford Public School (1256)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Upper Hunter
LOCAL GOVERNMENT AREA:	Upper Hunter

1256 - Blandford Public School
Site Plan (12347)









1:511

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Clerical Office - (28.94 SQM)	 Office (7)	
B00A - R0004 - Staff Room - (15.48 SQM)	 Office (3)	
B00A - R0006 - Principal - (12.19 SQM)	 Office (3)	
B00A - R0007 - Interview - (8.81 SQM)	 Office (2)	
B00B - R0001 - Movement - (17.9 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Home Base - (66.98 SQM) - Teaching Space: 1	 Student Space (31)	
B00G - R0002 - Home Base - (60.53 SQM) - Teaching Space: 1	 Student Space (28)	