


VENTILATION AUDIT REPORT

SCHOOL:	Blighty Public School (1261)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Edward River

1261 - Blighty Public School
Site Plan (13382)











1:499

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Withdrawal Space - 1hb - (7.04 SQM)	 Student Space (3)	
B00A - R0002 - Home Base - (46.95 SQM) - Teaching Space: 1	 Student Space (21)	
B00A - R0005 - Principal - (9.38 SQM)	 Office (2)	
B00A - R0007 - Movement - (31.71 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Principal - (10.94 SQM)	 Office (2)	
B00A - R0009 - Clerical Office/Workroom - (35.24 SQM)	 Office (8)	
B00B - R0001 - Movement - (20.31 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Movement - (15.61 SQM)	Not Applicable	Circulation or storage space.
B00C - R0003 - Home Base - (35.25 SQM) - Teaching Space: 1	 Student Space (16)	
B00C - R0004 - Practical Activities - 1hb - (21.95 SQM)	 Student Space (10)	
B00F - R0001 - Reading Area - (59.84 SQM)	 Student Space (27)	