

VENTILATION AUDIT REPORT







SCHOOL:	Bobin Public School (1269)
AMU REGION:	North Coast
STATE ELECTORATE:	Myall Lakes
LOCAL GOVERNMENT AREA:	Mid-Coast

1269 - Bobin Public School
Site Plan (13023)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00D - R0001 - Special Programs Room - (20.23 SQM)	 Student Space (9)	
B00D - R0002 - Reading Area - (39.37 SQM)	 Student Space (18)	
B00D - R0004 - Practical Activities - 1hb - (5.51 SQM)	 Student Space (2)	
B00D - R0005 - Seminar/Study - (14.44 SQM)	 Office (3)	
OS 505 16182 - OS 505 16182 - Admin Staff/Principal/Secure Store - (76 SQM)	 Office (19)	
OS 606 17513 - OS 606 17513 - Learning Unit - Standard With P.A.A A/C - (76 SQM)	 Student Space (35)	