

VENTILATION AUDIT REPORT

SCHOOL:	Bobs Farm Public School (1271)
AMU REGION:	Hunter/Central Coast
STATE ELECTORATE:	Port Stephens
LOCAL GOVERNMENT AREA:	Port Stephens

1271 - Bobs Farm Public School
Site Plan (10902)









1:514

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Reading Area - (39.95 SQM)	 Student Space (18)	
B00A - R0004 - Staff Room - (8.35 SQM)	 Office (2)	
B00A - R0005 - Clerical Office/Workroom - (12.02 SQM)	 Office (3)	
B00C - R0001 - Movement - (19.97 SQM)	Not Applicable	Circulation or storage space.
B00J - R0001 - Canteen - (12.76 SQM)	Not Applicable	Circulation or storage space.
OS 505 10273 - OS 505 10273 - Admin Staff/Principal/Secure Store - (76 SQM)	 Office (19)	
OS 602 12103 - OS 602 12103 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	
OS 602 15537 - OS 602 15537 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	