VENTILATION AUDIT REPORT



SCHOOL:	Bogan Gate Public School (1274)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Orange
LOCAL GOVERNMENT AREA:	Parkes

1274 - Bogan Gate Public School Site Plan (10146)



Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Clerical Office - (10.91 SQM)	Office (2)	
B00A - R0004 - Principal - (15.44 SQM)	Office (3)	
B00A - R0005 - Movement - (24.86 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Staff Room - (11.48 SQM)	Office (2)	
B00B - R0003 - Home Base - (45.89 SQM) - Teaching Space: 1	Student Space (21)	
B00B - R0004 - Home Base - (46.3 SQM) - Teaching Space: 1	Student Space (21)	
B00B - R0005 - Home Base - (45.87 SQM) - Teaching Space: 1	Student Space (21)	
B00B - R0007 - Movement - (51.6 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Reading Area - (59.86 SQM)	Student Space (27)	