


VENTILATION AUDIT REPORT

SCHOOL:	Booligal Public School (1303)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Hay

1303 - Booligal Public School
Site Plan (10162)



1:489

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (22.8 SQM)	Not Applicable	Circulation or storage space.
B00A - R0003 - Home Base - (48.69 SQM) - Teaching Space: 1	● Student Space (22)	
B00A - R0007 - Clerical Office - (8.07 SQM)	● Office (2)	
B00A - R0008 - Principal - (8.22 SQM)	● Office (2)	
B00D - R0001 - Reading Area - (59.86 SQM)	● Student Space (27)	