


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Boomi Public School (1307)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Northern Tablelands</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Moree Plains</b>

1307 - Boomi Public School  
Site Plan (11427)









1:790

Printed: 20-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Movement - (179.31 SQM)	Not Applicable	Circulation or storage space.
B00A - R1001 - Clerical Office/Workroom - (25.17 SQM)	 Office (6)	
B00A - R1002 - Principal - (10.94 SQM)	 Office (2)	
B00A - R1004 - Home Base - (53.79 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R1008 - Reading Area - (53.94 SQM)	 Student Space (25)	
B00A - R1012 - Movement - (13.66 SQM)	Not Applicable	Circulation or storage space.
B00A - R1014 - Special Programs Room - (14.77 SQM)	 Student Space (6)	
B00B - R0003 - Canteen - (20.16 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Home Base - (60.02 SQM) - Teaching Space: 1	 Student Space (27)	