

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Borenore Public School (3504)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Orange</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Cabonne</b>

3504 - Borenore Public School  
Site Plan (11964)












1:508

Printed: 21-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Clerical Office - (6.8 SQM)	 Office (1)	
B00A - R0002 - Principal - (13.24 SQM)	 Office (3)	
B00A - R0003 - Entry Vestibule - (6.8 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Home Base - (56.18 SQM) - Teaching Space: 1	 Student Space (26)	
B00A - R0006 - Entry Vestibule - (8.61 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Home Base - (43.61 SQM) - Teaching Space: 1	 Student Space (20)	
B00B - R0003 - Movement - (20.52 SQM)	Not Applicable	Circulation or storage space.
B00B - R0006 - Interview - (12.8 SQM)	 Office (3)	
B00B - R0007 - Staff Room - (13.36 SQM)	 Office (3)	
B00B - R0008 - Practical Activities - 1hb - (17.23 SQM)	 Student Space (7)	
B00B - R0009 - Staff Kitchen - (10.72 SQM)	 Office (2)	
B00B - R0010 - Movement - (8.6 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Reading Area - (59.17 SQM)	 Student Space (27)	