


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Botany Bay Environmental Education Centre (5741)</b>
<b>AMU REGION:</b>	<b>Sydney</b>
<b>STATE ELECTORATE:</b>	<b>Cronulla</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Sutherland</b>

5741 - Kamay Botany Bay Environment Education Centre  
Site Plan (13476)



## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00B - R0002 - Clerical Office - (27 SQM)	 Office (6)	
B00B - R0003 - Clerical Office - (11.01 SQM)	 Office (2)	
B00B - R0005 - Home Base - (99.18 SQM) - Teaching Space: 1	 Student Space (46)	
B00B - R0011 - Staff Kitchen - (15.72 SQM)	 Office (3)	