

VENTILATION AUDIT REPORT

SCHOOL:	Bourke-Walgett School of Distance Education (4644)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Bourke

Siteplan

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Reading Area - (91.2 SQM)	● Student Space (42)	
OS 601 12282 - OS 601 12282 - Learning Unit - Standard/Withdrawal - (76 SQM)	● Student Space (35)	
OS 601 13771 - OS 601 13771 - Learning Unit - Standard/Withdrawal - (76 SQM)	● Student Space (35)	
OS 601 13772 - OS 601 13772 - Learning Unit - Standard/Withdrawal - (76 SQM)	● Student Space (35)	
OS 751 11543 - OS 751 11543 - Learning Unit - ESL - (76 SQM)	● Student Space (35)	