




# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Bourke Tutorial Centre (793)</b>
<b>AMU REGION:</b>	<b>North Western NSW</b>
<b>STATE ELECTORATE:</b>	<b>Wollongong</b>
<b>LOCAL GOVERNMENT AREA:</b>	

Siteplan

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00J - R0002 - Independent Learning Space - (20.52 SQM)	 Student Space (9)	
B00J - R0004 - Seminar Space - (12.14 SQM)	 Office (3)	
B00J - R0007 - Food/Research Space - (7.26 SQM)	Not Applicable	Circulation or storage space.
B00J - R0008 - Food/Research Space - (13.06 SQM)	Not Applicable	Circulation or storage space.
B00J - R0013 - Staff Study - (14.18 SQM)	 Office (3)	
B00J - R0014 - Movement - (8.56 SQM)	Not Applicable	Circulation or storage space.
B00J - R0015 - Movement - (32.49 SQM)	Not Applicable	Circulation or storage space.
B00J - R0016 - Movement - (39.55 SQM)	Not Applicable	Circulation or storage space.