


VENTILATION AUDIT REPORT

SCHOOL:	Bournda Environmental Education Centre (5679)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Bega
LOCAL GOVERNMENT AREA:	Bega Valley

5679 - Bournda Environmental Education Centre
Site Plan (14698)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00B - R0002 - Movement - (18.09 SQM)	Not Applicable	Circulation or storage space.
B00B - R0003 - Staff Kitchen - (5.19 SQM)	<input checked="" type="radio"/> Office (1)	
B00E - R0001 - Movement - (13.22 SQM)	Not Applicable	Circulation or storage space.
B00E - R0002 - Clerical Office - (38.86 SQM)	<input checked="" type="radio"/> Office (9)	
B00E - R0004 - Clerical Office - (5.66 SQM)	<input checked="" type="radio"/> Office (1)	