

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Bredbo Public School (1347)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Monaro</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Snowy Monaro</b>



1347 - Bredbo Public School  
Site Plan (12438)








1:939

Printed: 20-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0003 - Movement - (6.96 SQM)	Not Applicable	Circulation or storage space.
B00A - R0004 - Clerical Office/Workroom - (38.22 SQM)	 Office (9)	
B00A - R0005 - Staff Room - (16.81 SQM)	 Office (4)	
B00B - R0001 - Movement - (10.64 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Reading Area - (39.94 SQM)	 Student Space (18)	
B00E - R0003 - Reading Area - (61.06 SQM)	 Student Space (28)	
OS 601 12204 - OS 601 12204 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	