


VENTILATION AUDIT REPORT

SCHOOL:	Bribbaree Public School (1354)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Hilltops

1354 - Bribbaree Public School
Site Plan (12451)



1:766

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (29.96 SQM)	Not Applicable	Circulation or storage space.
B00A - R0005 - Clerical Office/Workroom - (11.1 SQM)	Office (2)	
B00A - R0007 - Home Base - (69.78 SQM) - Teaching Space: 1	Student Space (32)	
B00A - R0008 - Principal - (16.6 SQM)	Office (4)	
B00B - R0001 - Movement - (14.28 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Clerical Office - (52.33 SQM)	Office (13)	
B00B - R0005 - Staff Room - (8.11 SQM)	Office (2)	
B00D - R0001 - Canteen - (8.59 SQM)	Not Applicable	Circulation or storage space.
B00D - R0002 - Practical Activities - 1hb - (14.52 SQM)	Student Space (6)	
B00D - R0003 - Home Base - (41.52 SQM) - Teaching Space: 1	Student Space (19)	
B00D - R0004 - Withdrawal Space - 1hb - (15.18 SQM)	Student Space (7)	
B00D - R0005 - Movement - (18.8 SQM)	Not Applicable	Circulation or storage space.
B00H - R0001 - Reading Area - (59.86 SQM)	Student Space (27)	