

VENTILATION AUDIT REPORT

SCHOOL:	Broadwater Public School (1361)
AMU REGION:	North Coast
STATE ELECTORATE:	Clarence
LOCAL GOVERNMENT AREA:	Richmond Valley

1361 - Broadwater Public School
Site Plan (12394)











1:600

Printed: 23-Dec-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0002 - Staff Room - (27.99 SQM)	 Office (6)	
B00A - R0004 - Canteen - (13.32 SQM)	Not Applicable	Circulation or storage space.
B00A - R0011 - Movement - (15.98 SQM)	Not Applicable	Circulation or storage space.
B00A - R1001 - Movement - (11.82 SQM)	Not Applicable	Circulation or storage space.
B00A - R1002 - Clerical Office/Workroom - (13.61 SQM)	 Office (3)	
B00A - R1004 - Withdrawal Space - 1hb - (14.48 SQM)	 Student Space (6)	
B00A - R1005 - Home Base - (56.64 SQM) - Teaching Space: 1	 Student Space (26)	
B00A - R1007 - Withdrawal Space - 1hb - (11.75 SQM)	 Student Space (5)	
B00B - R0003 - Movement - (26.08 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Home Base - (60.74 SQM) - Teaching Space: 1	 Student Space (28)	
OS 503 11066 - OS 503 11066 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	 Office (38)	
OS 602 15316 - OS 602 15316 - Learning Unit - Standard With P.A.A. - (76 SQM)	 Student Space (35)	