

VENTILATION AUDIT REPORT

SCHOOL:	Broken Hill Tutorial Centre (888)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	

Siteplan

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Staff Kitchen - (6.72 SQM)	Office (1)	
B00A - R0003 - Staff Study - (13.33 SQM)	Office (3)	
B00A - R0004 - Independent Learning Space - (53.29 SQM)	Student Space (24)	
B00A - R0005 - Independent Learning Space - (54.37 SQM)	Student Space (25)	