
VENTILATION AUDIT REPORT



SCHOOL:	Brungle Public School (1387)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Wagga Wagga
LOCAL GOVERNMENT AREA:	Snowy Valleys





Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with COVID safe school operations. It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces. The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (12.69 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Staff Room - (25.64 SQM)	Office (6)	
B00A - R0003 - Staff Kitchen - (10 SQM)	Office (2)	
B00B - R0001 - Home Base - (53.44 SQM) - Teaching Space: 1	Student Space (24)	
B00B - R0003 - Interview/Meeting - (15.19 SQM)	Office (3)	
B00B - R0004 - Reading Area - (24.94 SQM)	Student Space (11)	
B00H - R0001 - Reading Area - (59.63 SQM)	Student Space (27)	
B00J - R0001 - Entry Vestibule - (7.21 SQM)	Not Applicable	Circulation or storage space.
B00J - R0002 - Movement - (7.39 SQM)	Not Applicable	Circulation or storage space.
B00J - R0003 - Principal - (18.99 SQM)	Office (4)	
B00J - R0004 - Clerical Office - (12.5 SQM)	Office (3)	
B00J - R0008 - Staff Room - (12.43 SQM)	Office (3)	
B00J - R0009 - Clerical Office - (20.43 SQM)	Office (5)	
B00J - R0010 - Sick Bay - (6.72 SQM)	Student Space (3)	