

VENTILATION AUDIT REPORT

SCHOOL:	Bungwahl Public School (1424)
AMU REGION:	North Coast
STATE ELECTORATE:	Myall Lakes
LOCAL GOVERNMENT AREA:	Mid-Coast

1424 - Bungwahl Public School
Site Plan (10309)










1:836

Printed: 01-Jun-2021

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Practical Activities - 1hb - (15.89 SQM)	 Student Space (7)	
B00A - R0002 - Home Base - (62.43 SQM) - Teaching Space: 1	 Student Space (28)	
B00A - R0005 - Reading Area - (12.32 SQM)	 Student Space (5)	
B00A - R0006 - Practical Activities - (17.44 SQM)	 Student Space (8)	
B00B - R0001 - Movement - (159.65 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Canteen - (32.28 SQM)	Not Applicable	Circulation or storage space.
B00E - R0001 - Practical Activities - 1hb - (16.52 SQM)	 Student Space (7)	
B00E - R0002 - Home Base - (43.87 SQM) - Teaching Space: 1	 Student Space (20)	
B00G - R0001 - Canteen - (30.27 SQM)	Not Applicable	Circulation or storage space.
OS 503 13741 - OS 503 13741 - Admin Lib Staff/Principal/Clerk/Store - (152 SQM)	 Office (38)	