


VENTILATION AUDIT REPORT

SCHOOL:	Bunnaloo Public School (1425)
AMU REGION:	Southern NSW
STATE ELECTORATE:	Murray
LOCAL GOVERNMENT AREA:	Murray River

1425 - Bunnaloo Public School
Site Plan (12410)











1:875

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (19.3 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Home Base - (41.47 SQM) - Teaching Space: 1	 Student Space (19)	
B00B - R0001 - Movement - (13.74 SQM)	Not Applicable	Circulation or storage space.
B00B - R0002 - Home Base - (53.12 SQM) - Teaching Space: 1	 Student Space (24)	
B00B - R0004 - Practical Activities - 1hb - (12.58 SQM)	 Student Space (5)	
B00B - R0005 - Withdrawal Space - 1hb - (8.47 SQM)	 Student Space (3)	
B00C - R0001 - Home Base - (52.61 SQM) - Teaching Space: 1	 Student Space (24)	
B00C - R0003 - Withdrawal Space - 1hb - (8.57 SQM)	 Student Space (3)	
B00C - R0004 - Movement - (25.11 SQM)	Not Applicable	Circulation or storage space.
B00G - R0005 - Reading Area - (90.9 SQM)	 Student Space (42)	
OS 500 18104 - OS 500 18104 - Admin - Library - (133 SQM)	 Office (33)	