


# VENTILATION AUDIT REPORT












<b>SCHOOL:</b>	<b>Cabbage Tree Island Public School (1471)</b>
<b>AMU REGION:</b>	<b>North Coast</b>
<b>STATE ELECTORATE:</b>	<b>Ballina</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Ballina</b>

1471 - Cabbage Tree Island Public School  
Site Plan (12201)



## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0006 - Home Base - (53.29 SQM) - Teaching Space: 1	 Student Space (24)	
B00A - R0007 - Practical Activities - 1hb - (17.67 SQM)	 Student Space (8)	
B00A - R0008 - Staff Room - (11.71 SQM)	 Office (2)	
B00A - R0009 - Principal - (11.83 SQM)	 Office (2)	
B00A - R0013 - Clerical Office - (7.58 SQM)	 Office (1)	
B00A - R0014 - Principal - (10.38 SQM)	 Office (2)	
B00A - R0015 - Staff Room - (13.98 SQM)	 Office (3)	
B00A - R0016 - Movement - (7.58 SQM)	Not Applicable	Circulation or storage space.
B00C - R0002 - Home Base - (67.11 SQM) - Teaching Space: 1	 Student Space (31)	
B00D - R0001 - Home Base - (59.86 SQM) - Teaching Space: 1	 Student Space (27)	
OS 531 13128 - OS 531 13128 - Library - (76 SQM)	 Student Space (35)	
OS 711 16822 - OS 711 16822 - Home Science/Art/Science Dem/Computer - (95 SQM)	 Student Space (44)	