







VENTILATION AUDIT REPORT

SCHOOL:	Campbelltown Suspension Centre (926)
AMU REGION:	South Western Sydney
STATE ELECTORATE:	
LOCAL GOVERNMENT AREA:	

Siteplan

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00L - R0001 - Administration - Clerical - (18.69 SQM)	 Office (4)	
B00N - R0002 - Movement - (6.66 SQM)	Not Applicable	Circulation or storage space.
B00N - R0004 - Computer Room - (14.34 SQM)	 Student Space (6)	
B00N - R0005 - Administration - Clerical - (30.17 SQM)	 Office (7)	
B00N - R0009 - Administration - Clerical - (16.1 SQM)	 Office (4)	
B00N - R0010 - Administration - Clerical - (10.72 SQM)	 Office (2)	
B00N - R0011 - Administration - Clerical - (10.75 SQM)	 Office (2)	