


# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Caniaba Public School (1492)</b>
<b>AMU REGION:</b>	<b>North Coast</b>
<b>STATE ELECTORATE:</b>	<b>Lismore</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Lismore</b>

1492 - Caniaba Public School  
Site Plan (10141)













1:700

Printed: 03-Feb-2021

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0004 - Staff Room - (11.12 SQM)	 Office (2)	
B00A - R0012 - Home Base - (71.29 SQM) - Teaching Space: 1	 Student Space (33)	
B00A - R0014 - Canteen - (14.15 SQM)	Not Applicable	Circulation or storage space.
B00A - R0015 - Home Base - (74.56 SQM) - Teaching Space: 1	 Student Space (34)	
B00F - R0002 - Clerical Office - (19.12 SQM)	 Office (4)	
B00F - R0004 - Sick Bay - (7.6 SQM)	 Student Space (3)	
B00F - R0007 - Movement - (19.52 SQM)	Not Applicable	Circulation or storage space.
B00F - R0008 - Staff Room - (21.43 SQM)	 Office (5)	
B00F - R0009 - Staff Kitchen - (5.2 SQM)	 Office (1)	
B00F - R0011 - Principal - (17.18 SQM)	 Office (4)	
B00F - R0012 - Reading Area - (72.02 SQM)	 Student Space (33)	
OS 601 15361 - OS 601 15361 - Learning Unit - Standard/Withdrawal - (76 SQM)	 Student Space (35)	