











VENTILATION AUDIT REPORT

SCHOOL:	Canley Vale Tutorial Centre (728)
AMU REGION:	South Western Sydney
STATE ELECTORATE:	Fairfield
LOCAL GOVERNMENT AREA:	

Siteplan

Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00S - R0001 - Movement - (7.17 SQM)	Not Applicable	Circulation or storage space.
B00S - R0002 - Staff Study - (14.61 SQM)	 Office (3)	
B00S - R0004 - Seminar - Type 1 - (17.11 SQM)	 Office (4)	
B00S - R0005 - Tutorial Centre - (19.31 SQM)	 Student Space (8)	
B00S - R0006 - Commonroom - (19.32 SQM)	 Office (4)	
B00S - R0007 - Seminar - Type 1 - (15.19 SQM)	 Office (3)	
B00S - R0008 - Seminar Space - (13.21 SQM)	 Office (3)	
B00S - R0009 - Staff Kitchen - (11.77 SQM)	 Office (2)	
B00S - R0015 - Independent Learning Space - (21.14 SQM)	 Student Space (9)	
B00S - R0016 - Movement - (15.83 SQM)	Not Applicable	Circulation or storage space.
OS 711 10756 - OS 711 10756 - Home Science/Art/Science Dem/Computer - (95 SQM)	 Student Space (44)	
OS 751 14256 - OS 751 14256 - Learning Unit - ESL - (76 SQM)	 Student Space (35)	