
## **VENTILATION AUDIT REPORT**



SCHOOL:	Caragabal Public School (1503)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Cootamundra
LOCAL GOVERNMENT AREA:	Weddin

1503 - Caragabal Public School Site Plan (12217)



## **Ventilation Audit Key**

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
0	Category B  This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> .  The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (108.32 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Clerical Office - (23 SQM)	Office (5)	
B00A - R0005 - Movement - (39.15 SQM)	Not Applicable	Circulation or storage space.
B00A - R0006 - Staff Room - (13.56 SQM)	Office (3)	
B00A - R0008 - Sick Bay - (6.53 SQM)	Student Space (3)	
B00A - R0009 - Home Base - (60.78 SQM) - Teaching Space: 1	Student Space (28)	
B00A - R0011 - Reading Area - (58.57 SQM)	Student Space (27)	
B00A - R0013 - Movement - (13.4 SQM)	Not Applicable	Circulation or storage space.
B00A - R0016 - Movement - (7.84 SQM)	Not Applicable	Circulation or storage space.
B00A - R0017 - Home Base - (61.04 SQM) - Teaching Space: 1	Student Space (28)	
B00A - R0018 - Practical Activities - 1hb - (31.21 SQM)	Student Space (14)	
B00A - R0019 - Principal - (14.14 SQM)	Office (3)	
B00A - R0021 - Entry Vestibule - (11.18 SQM)	Not Applicable	Circulation or storage space.
B00C - R0001 - Home Base - (59.89 SQM) - Teaching Space: 1	Student Space (27)	