

## **VENTILATION AUDIT REPORT**



SCHOOL:	Carcoar Public School (1504)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Bathurst
LOCAL GOVERNMENT AREA:	Blayney





## Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
$\bigcirc$	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Home Base - (52.61 SQM) - Teaching Space: 1	Student Space (24)	
B00A - R0002 - Home Base - (56.77 SQM) - Teaching Space: 1	Student Space (26)	
B00A - R0003 - Sick Bay - (7.53 SQM)	Student Space (3)	
B00A - R0004 - Movement - (12.58 SQM)	Not Applicable	Circulation or storage space.
B00A - R0005 - Movement - (27.45 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Clerical Office - (21.99 SQM)	Office (5)	
B00A - R0009 - Movement - (12.12 SQM)	Not Applicable	Circulation or storage space.
B00B - R0001 - Communal Space - (89.89 SQM)	Student Space (41)	
B00B - R0003 - Movement - (96.1 SQM)	Not Applicable	Circulation or storage space.
B00B - R0004 - Reading Area - (27.08 SQM)	Student Space (12)	
B00B - R0005 - Duplicating Workroom - (12.95 SQM)	Office (3)	
B00B - R0012 - Staff Room - (14.32 SQM)	Office (3)	