
VENTILATION AUDIT REPORT



SCHOOL:	Carinda Public School (1507)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Barwon
LOCAL GOVERNMENT AREA:	Walgett



Meters

1:776

1/3

Printed: 20-Mar-2020

Ventilation Audit Key

Category	Description	
	Category A Operate this space in line with <u>COVID safe school operations</u> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.	
•	Category B This space should be occupied at 1 person per 4m ² to comply with <u>COVID safe school operations and the guided use of spaces</u> . The report details the number of people who can be accommodated safely in each of the identified spaces.	

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Movement - (21.46 SQM)	Not Applicable	Circulation or storage space.
B00A - R0002 - Movement - (75.04 SQM)	Not Applicable	Circulation or storage space.
B00A - R0003 - Staff Study - (27.95 SQM)	Office (6)	
B00A - R0005 - Movement - (145.95 SQM)	Not Applicable	Circulation or storage space.
B00A - R0008 - Movement - (27.52 SQM)	Not Applicable	Circulation or storage space.
B00A - R1001 - Movement - (84.63 SQM)	Not Applicable	Circulation or storage space.
B00A - R1002 - Principal - (13.98 SQM)	Office (3)	
B00A - R1004 - Staff Room - (9.7 SQM)	Office (2)	
B00A - R1005 - Clerical Office - (9.48 SQM)	Office (2)	
B00A - R1006 - Raised Platform - (16.41 SQM)	Not Applicable	Circulation or storage space.
B00A - R1012 - Movement - (6.99 SQM)	Not Applicable	Circulation or storage space.
B00A - R1019 - Reading Area - (52.44 SQM)	Student Space (24)	
B00A - R1020 - Home Base - (51.93 SQM) - Teaching Space: 1	Student Space (24)	
B00A - R1021 - Home Base - (52.36 SQM) - Teaching Space: 1	Student Space (24)	
B00B - R0001 - Movement - (21 SQM)	Not Applicable	Circulation or storage space.