

# VENTILATION AUDIT REPORT

<b>SCHOOL:</b>	<b>Carrathool Public School (1517)</b>
<b>AMU REGION:</b>	<b>Southern NSW</b>
<b>STATE ELECTORATE:</b>	<b>Murray</b>
<b>LOCAL GOVERNMENT AREA:</b>	<b>Carrathool</b>

1517 - Carrathool Public School  
Site Plan (12227)








1:786

Printed: 20-Mar-2020

## Ventilation Audit Key

Category	Description
	Category A Operate this space in line with <a href="#">COVID safe school operations</a> . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m <sup>2</sup> to comply with <a href="#">COVID safe school operations and the guided use of spaces</a> . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0005 - Principal - (20.84 SQM)	 Office (5)	
B00A - R0007 - Practical Activities - 1hb - (16.82 SQM)	 Student Space (7)	
B00A - R0009 - Home Base - (83.08 SQM) - Teaching Space: 1	 Student Space (38)	
B00A - R0010 - Movement - (5.03 SQM)	Not Applicable	Circulation or storage space.
B00A - R0011 - Staff Room - (14.68 SQM)	 Office (3)	
B00E - R0001 - Reading Area - (59.86 SQM)	 Student Space (27)	