


VENTILATION AUDIT REPORT








SCHOOL:	Carroll Public School (1520)
AMU REGION:	North Western NSW
STATE ELECTORATE:	Tamworth
LOCAL GOVERNMENT AREA:	Gunnedah

1520 - Carroll Public School
Site Plan (12228)



Ventilation Audit Key

Category	Description
	Category A Operate this space in line with COVID safe school operations . It has the required level of natural ventilation. NB. Circulation and storage areas should not be used for groups or gatherings.
	Category B This space should be occupied at 1 person per 4m ² to comply with COVID safe school operations and the guided use of spaces . The report details the number of people who can be accommodated safely in each of the identified spaces.

Entity Location	Audit Condition Classification (Capacity)	Comment
B00A - R0001 - Special Programs Room - (43.18 SQM)	 Student Space (20)	
B00A - R0002 - Movement - (79.22 SQM)	Not Applicable	Circulation or storage space.
B00A - R1001 - Staff Room - (11.07 SQM)	 Office (2)	
B00A - R1002 - Home Base - (43.69 SQM) - Teaching Space: 1	 Student Space (20)	
B00A - R1003 - Home Base - (44.02 SQM) - Teaching Space: 1	 Student Space (20)	
B00A - R1004 - Principal - (11.12 SQM)	 Office (2)	
B00A - R1005 - Movement - (10.4 SQM)	Not Applicable	Circulation or storage space.
B00A - R1006 - Reading Area - (11.24 SQM)	 Student Space (5)	
B00B - R0001 - Movement - (16.62 SQM)	Not Applicable	Circulation or storage space.
B00D - R0001 - Communal Space - (59.96 SQM)	 Student Space (27)	